04.2023

LP2000 TYPE* IGNITION SYSTEMS SERVICE BULLETIN 2023

Low Pressure Ballistic Ignition System(BIS)/ Pyrotechnical Ignition System(PTIS)

Recommended Service to be preformed by supplier:

- To ensure reliable operation and to reduce downtime and disturbances we recommend the following yearly/bi-yearly maintenance of the Ignition System:
- . Control/correct/Allign Magazine (yearly).
 - Check Rotation
 - Check Centering
 - Check Wearing Parts (Index plate, cyllinder edges, etc)
 - · Change Magazine O-ring (bi-yearly)
- . Control and Maintenance of Pellet Tube (yearly).
 - Clean Pellet Tube with Dummy Pellets
 - Control of Pellet Tube with Brass Pig
 - Re-connect Pellet Tube and test with live LP2000
- . Check System/Cabinet Integrity(yearly)
- Check Launching Valve Integrity (yearly)
- . Check Check-Valves Integrity (bi-yearly)
- General tubing/fittings Integrity Check (yearly)
- . Check and Control of Purge Air (yearly)
- Control and test of VA-Meter (yearly)
- . Test of low-alarm on VA-Meter (yearly)



